



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2006 – 2009 Yamaha FJR1300

Conditions: The operator of the vehicle may observe various electrical functions operating erratically up to and including stalling and being unable to restart the vehicle.

Cause: A potential cause for the above conditions is a fault in the ground connector overheating and making intermittent contact.

Correction: Follow the manufacturer's recommended repair procedure, which includes installing an additional lead to ground and replacing the original ground lead if already damaged.

