



TECH TIPS

Dixie Part Numbers: S-8772 S-80464 TBA

Applications: 2007 – 2011 Toyota Camry (Engine 2AZ and 2AR)
2009 – 2011 Toyota Corolla (all models)
2009 – 2011 Toyota Matrix (all models)

Conditions: The operator of the vehicle may complain that the engine cranks for an extended period without starting or that the engine cranks and only starts after an extended period. The condition will exhibit itself when the vehicle is operated at high altitudes, at high temperatures or when the vehicle has been subject to heavy loads.

Cause: A potential cause for the above condition is a flaw in the fuel pump design.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures which include upgrading the fuel pump to a newer version.

