



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2009 – 2010 Infiniti EX35

**Conditions:** The operator of the vehicle may complain that the engine fails to start or that warning lights are on. The technician will be unable to find any trouble codes stored in the system memory and the warning being indicated does not represent an actual problem.

**Cause:** A potential cause for the above condition is water penetrating into the wiring harness, creating corrosion and fretting problems.

**Correction:** Follow the manufacturer's recommended inspection, diagnostic and repair procedures when necessary. Just as a warning, the job is "listed" as 1.5 hours and the instructions are 29 pages long.

