



# TECH TIPS

---

**Dixie Part Numbers:** S-80280

**Applications:** 2008 Cadillac SRX

**Conditions:** The operator of the vehicle may comment on an intermittent no start condition. The technician, when replacing the starter battery cable, may notice that the replacement battery cable is shorter than the cable being removed.

**Cause:** A potential cause for the above condition is the routing for the starter battery cable has been changed to prevent chaffing.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures when applicable.

