



TECH TIPS

Dixie Part Numbers: S-8227 TBA

Applications: 2008 – 2012 Scion xB (2AZ-FE 2WD)

Conditions: The operator of the vehicle may complain of long cranking periods and a failure to start at high altitude, high temperature or under heavy loads.

Cause: A possible cause for the above conditions is an inadequate fuel pump resulting in the engine starving for fuel.

Correction: Follow the manufactures recommended diagnostic and repair procedures which include replacing the fuel pump and filter assembly with part number 23220-37030 (was 23220-37120).

