



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2010 Honda Accord 2 door (VIN 1HGCS1..AA003602 to VIN 1HGCS1..AA004331)  
2010 Honda Accord 4 door (VIN 1HGCP2..AA037687 to VIN 1HGCP2..AA043947)  
2010 Honda CR-V 2WD (VIN 5J6RE3..AL005827 to VIN 5J6RE3..AL006366)  
2010 Honda CR-V 4WD (VIN 5J6RE4..AL011857 to VIN 5J6RE3..AL011916)

**Conditions:** The operator of the vehicle may complain of the engine stalling and failing to restart or cranking without starting.

**Cause:** A possible cause for the above conditions a loose wire connection in the C101 engine wiring harness.

**Correction:** Follow the manufactures recommended diagnostic and repair procedures which include inspecting the VIN in the engine compartment, vehicles already inspected and repaired by the dealership network will have a punch mark above the first digit.