



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2012 Acura TL 2WD VIN 19UUA8...CA000001 to  
19UUA8...CA008239.  
2012 Acura TL SH-AWD VIN 19UUA9...CA000001 to  
19UUA8...CA002516.

**Conditions:** The operator of the vehicle may complain that the malfunction indicator display has the message "Battery Charge Low" intermittently. The technician will not find any issues with the battery or charging system.

**Cause:** A potential cause is the battery sensor software, which uses factors such as ambient temperature to calculate the battery's state of charge.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedure, which first includes verifying that the electrical system is functioning correctly and re-flashing the battery sensor pack when applicable.