



TECH TIPS

Dixie Part Numbers: A-80349

Applications: 2007 Toyota Yaris

Condition: The charge system warning light may indicate charge system errors.

Cause: A potential cause for this is corrosion in the alternator on the voltage regulator terminals.

Correction: The manufacturer recommends changing the voltage regulator or the alternator.

Revision 20090819 Corrected part number