



# TECH TIPS

**Dixie Part Numbers:** S-8768, S-8769, S-8990 and S-8996

**Applications:** 1999 – 2000 Chevrolet Tracker

**Condition:** Some vehicle operators may complain of slow or no start conditions in extreme cold weather.

**Cause:** The manufacture has made several running changes to improve cold weather starting.

**Correction:** Ensure that all parts/system are to the most current revision:

- The manufacturer recommends using NGK Iridium plugs (GM part number 91175704).
- The factory-supplied battery was rated for 550CCA and the manufacturer recommends that this be increased to 600CCA.
- The PCM must be reprogrammed to the latest information.

Follow the manufacturer's recommended procedures when performing the above updates.

