



TECH TIPS

Dixie Part Numbers: S-8775 S-8985

Applications: 1999 – 2000 Mitsubishi Gallant
2000 Mitsubishi Eclipse

Condition: The owner of the vehicle may complain of a no start condition.

Cause: A potential cause for this is that the battery cable may be damaged by heat from the exhaust manifold.

Correction: Inspect the battery cables for damage and for the proper heat protector. Follow the manufacturer's recommended procedures for repairing this item. Mitsubishi Motor Sales America, Inc. did a voluntary recall to address this problem but there may still be some vehicles with this condition.

Rev: 20100211- Updated Part Numbers

REV: 20100211

Courtesy of APRA

TSB_838.doc

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.