



# TECH TIPS

**Dixie Part Numbers:** S-80246

**Applications:** MCI D / E / J Series Coaches

**Condition:** The vehicle operator may comment on one or more of the following conditions:

- The vehicle fails to start
- The vehicle intermittently will not crank
- Slow or hard cranking

**Cause:** A potential cause for this is moisture contaminating the relay switch mounted to the side of the starter.

**Correction:** The manufacturer recommends that for servicing vehicles that exhibit the above conditions that the terminals are replaced and coated with sealant after they are installed.

