



# TECH TIPS

**Dixie Part Numbers:** S-8738 S-8772

**Applications:** 2006 – 2010 Toyota RAV4  
2008 – 2009 Toyota Highlander  
2009 – 2010 Toyota Matrix

**Condition:** The operator of the vehicle may complain that the vehicle does not start intermittently or fails to start. Moving the shift lever in and out of the “Park” position may temporarily alleviate the problem.

**Cause:** A potential cause for the above condition is the neutral position switch assembly.

**Correction:** The manufacturer recommends replacing the neutral position switch assembly with a revised one. The part number for the revised neutral position switch is 84540-42010 for the above applications. Follow the manufacturer’s recommended procedures when performing the repairs.

