



TECH TIPS

Dixie Part Numbers: S-8772 S-80409

Applications: 2005 – 2008 Toyota Avalon
2007 – 2008 Toyota Camry
2007 – 2008 Toyota Camry HV
2008 Toyota Highlander
2008 Toyota Highlander HV
2008 Toyota Land Cruiser

Condition: The operator of the vehicle may complain of an intermittent no crank condition when attempting to start the vehicle from the pushbutton *Engine Start Stop* button on applications with conventional combustion engines only, or the *Power* button on hybrid applications.



Cause: A possible cause for the above condition is poor contacts in the switch.

Correction: The manufacturer has released newer switches with improved contacts to remedy this situation. Follow the manufacturer's recommended procedures for checking and replacing the *Engine Start Stop* button or the *Power* button.