



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 – 2010 Pontiac Vibe 2.4L

Condition: The operator of the vehicle may complain of one or both of the following conditions:

- There is an intermittent sharp noise at start up.
- There is an intermittent noise at idle

The technician may observe diagnostic code P0335 immediately after the noise is heard.

Cause: A potential cause for the above condition is the intake cam phaser not parking properly.

Correction: Follow the manufacturer's recommended procedures for diagnosing, inspecting, and if required replacing the air intake phaser.

