



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2009-2010 Hyundai Sonata 2.4L with Valeo Mexico Starters

**Condition:** The operator of the vehicle may complain of an intermittent no start condition when operating the vehicle below freezing conditions.

**Cause:** The solenoid was not manufactured to operate in sub-zero climates.

**Correction:** The manufacturer recommends replacing the solenoid or starter with one that will operate in colder climates.

