TECH TIPS

Dixie Part Numbers:

A-6505	A-80192	A-80302	A-80358
A-80359	A-80363	S-1497	S-1499
S-80280	S-80334	**TBA**	

Applications: 2006 – 2010 Chevrolet Impala with heated seats
2007 – 2009 Chevrolet Equinox with heated seats
2007 – 2009 Pontiac Torrent with heated seats

Condition: The operator of the vehicle may complain of an intermittent no crank, no start condition or of a low or dead battery.

Cause: A potential cause for the above condition may be the heated seat module. A programming flaw may cause the serial bus to remain active and prevent the modules from going into the sleep mode when the vehicle is shut off.

Correction: Follow the manufacturer's recommended procedures, which include reprogramming the heated seat module with the latest calibration files.

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.