TECH TIPS

Dixie Part Numbers:

A-766	A-778	A-788	A-792
A-795	A-796	A-1697	A-1698
A-1700	A-1701	A-1702	A-1704
A-6498	A-7001	A-7002	A-7007
S-8814	S-80234	TS-1758	TS-1767
101-24101	101-24104	101-24107	101-24201
160-55110	201-29103	201-38101	246-30115

Applications: 2005 – 2006 Thomas Built Buses

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- the vehicle fails to start
- the vehicle has caught on fire
- the battery is run down/dead

Cause: A potential cause for the above conditions is the main battery cable chaffing on a bracket next to the starter resulting in a short circuit to ground.

Correction: When working on a vehicle form the above applications inspect the main battery cable. Replace and re-route the battery cable if applicable.

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.