



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2009 – 2010 Cadillac CTS-V  
2009 – 2010 Chevrolet Corvette ZR1

**Condition:** The operator of the vehicle may complain that the belt squeals or squeaks.

**Cause:** A potential cause for the above condition is a misaligned belt.

**Correction:** Follow the manufacturer's recommended inspection procedures to ensure the belts are properly aligned. If required, replace the belts with the appropriate ones. The manufacturer lists 12636227 for the Cadillac CTS-V and 12637321 for the Chevrolet Corvette.

