



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2010 – 2011 Chevrolet Express G Series Van 6.6L Diesel  
2010 – 2011 Chevrolet Silverado 6.6L Diesel  
2010 – 2011 GMC Savana 6.6L Diesel  
2010 – 2011 GMC Sierra 6.6L Diesel

**Condition:** The operator of the vehicle may complain of a failure to start, a hard start or an extended crank cycle. After the engine starts it functions properly.

**Cause:** A potential cause for the above condition is the Filter Minder Vacuum Switch.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures.

