



# TECH TIPS

**Dixie Part Numbers:** S-1466 S-1495 S-1523 TBA

**Applications:** 2005 – 2010 Chevrolet Cobalt  
2006 Pontiac Pursuit  
2007 – 2010 Pontiac G5

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- The engine fails to crank.
- The engine cranks but does not start.
- There is an intermittent need for extra effort when steering.

The technician may note one or more of the following codes in the system:

P0575	P0700	P0703	P2544	U0073
U0212	U0140	U2100	U2105	U2106
U2107	U2108			

**Cause:** A possible cause for the above condition is that the wiring connections on the vehicle may have become loose.

**Correction:** Follow the manufacturers recommended diagnostic and repair procedures which include verifying proper ignition and ground to all modules that are not communicating properly and inspecting all plug connectors and ensuring that if OnStar® equipped, that this system is inspected as well.