



TECH TIPS

Dixie Part Numbers: A-1378 A-1382 A-1401 A-1402

Applications: 1992 – 1994 Cadillac DeVille 4.6L and 4.9L applications
1992 – 1994 Cadillac Eldorado 4.6L and 4.9L applications
1992 – 1994 Cadillac Seville 4.6L and 4.9L applications

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- A/C compressor moan
- Low alternator output
- Alternator failure

Cause: A possible cause for the above conditions is the A/C compressor hose and clutch driver assembly.

Correction: The manufacturer has released a revised clutch driver kit and hose kit as shown in the table below to alleviate the problem:

| Year | Engine | A/C Compressor Hose Assembly | Clutch Drive Kit |
|------|--------|------------------------------|------------------|
| 1992 | 4.9L | 25655631 | 6553791 |
| 1993 | 4.6L | 25655633 | 6553791 |
| 1993 | 4.9L | 25655362 | 6553791 |
| 1994 | 4.9L | 3542985 | 6553791 |

Follow the manufacturer's recommended procedures when changing the clutch drive kit and a/c compressor hose assembly.