



# TECH TIPS

**Dixie Part Numbers:**      A-1705      A-1758      A-6548      A-80198  
   A-80201      S-1468      S-1511      S-1515

**Applications:**      2006 – 2010 Cadillac DTS  
   2007 – 2010 Cadillac Escalade with heated rear seats  
   2007 – 2010 Cadillac Escalade ESV with heated rear seats  
   2007 – 2010 Chevrolet Suburban with heated rear seats  
   2007 – 2010 Chevrolet Tahoe with heated rear seats  
   2007 – 2010 GMC Yukon with heated rear seats  
   2007 – 2010 GMC Yukon XL with heated rear seats

**Condition:**      The operator of the vehicle may complain of one or more of the following conditions:

- No crank
- Slow crank
- No start
- Discharged or low battery

**Cause:**      A potential cause for the above conditions is the rear heated seats module discharging the battery by keeping the data line active after the ignition has been shut off.

**Correction:**      The manufacturer has released an updated calibration file for the rear heated seats module to correct the above situation.

REV:20101220 Added DTS application and associated unit numbers