



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2009 – 2010 Buick Enclave  
2009 – 2010 Chevrolet Traverse  
2009 – 2010 GMC Acadia  
2009– 2010 Saturn Outlook

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- A low or dead battery
- Slow or hard cranking during the start cycle

**Cause:** A potential cause for the above conditions is a flaw in the instrument panel cluster software that causes the panel to “wake-up” at inappropriate times.

**Correction:** The manufacturer has released a calibration file to correct the problem. Follow the manufacturer’s recommended diagnostic and repair procedure.

