



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2010 Buick LaCrosse  
2010 Cadillac SRX

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- The battery is low or dead.
- The engine cranks slowly or fails to crank or start.

**Cause:** A potential cause for the above condition is the push button start ignition system staying in the run cycle, even after the engine is turned off. This would cause excessive quiescent (parasitic) drain and, if left for an extended period would discharge the battery.

**Correction:** The software for the body control module and keyless entry control module have been revised to correct this problem. Follow the manufacturers recommended procedures for updating the software.

REV: 20110401 Added Buick LaCrosse Application