



# TECH TIPS

**Dixie Part Numbers:**      A-1759      A-80212      A-80214      A-80221  
   A-9503      S-6263      S-6276      S-6281  
   S-6282      S-6558

**Applications:**      2007 Audi A6 (VIN 000001 – 073265)  
   2007 Audi A8 (VIN 000001 – 010103)  
   2007 Audi Q7 (VIN 000001 – 063347)

**Condition:**      The operator of the vehicle may complain of one or more of the following conditions:

- The battery is low or discharged.
- The engine fails to crank or start

**Cause:**      A potential cause for the above condition is a software malfunction that prevents the radio receiver from entering the sleep mode.

**Correction:**      The manufacturer has released a software update to address this issue. Follow the manufacturer's recommended procedures for verifying and updating the software, when applicable.