



TECH TIPS

Dixie Part Numbers: A-215-6 A-217-6 A-221-6 A-232
 A-233 A-235 A-237 A-243
 A-254 A-255

Applications: 1987 – 1996 Ford Econoline 4.9L
 1987 – 1996 Ford F-Series 4.9L

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- Belt failure
- Belt loss
- Alternator failure
- Battery failure

Cause: An improperly aligned front-end accessory drive (FEAD) belt may cause the above conditions. The manufacturer has identified a problem with the idler pulley assembly.

Correction: The manufacturer recommends using idler pulley kit F6PZ-6K007-AA to correct the problem. Follow the manufacturer's instructions when installing the kit.