



TECH TIPS

Dixie Part Numbers: S-2136

Applications: 2011 Ford Fiesta

Conditions: The operator of the vehicle may complain that intermittently the engine fails to start due to the Passive Anti-Theft System locking the starter out. They may also observe shift flare when the automatic transmission shifts from 2nd to 3rd gear (the RPM's increase momentarily after shifting). The technician may find the code P1260 stored in the power train control module (PCM).

Cause: A potential cause for the above conditions is a flaw in the PCM programming.

Correction: Follow the manufacturer's recommended procedures to update the PCM programming to release 69.04 or higher when applicable.

