



TECH TIPS

Dixie Part Numbers: S-6175 S-6215 S-8439 S-8442
 S-8713 S-8714 S-8725 S-8749
 S-8750 S-8765

Applications: 1998 – 2000 Chrysler Sebring Convertible
 1998 – 2000 Jeep Wrangler
 1999 – 2000 Chrysler 300M
 1999 – 2000 Chrysler Concorde
 1999 – 2000 Chrysler Intrepid
 1999 – 2000 Chrysler LHS
 1999 – 2000 Dodge Stratus
 1999 – 2000 Dodge Intrepid
 1999 – 2000 Plymouth Breeze
 1999 – 2000 Jeep Grand Cherokee
 1999 – 2000 Jeep Cherokee
 2000 Chrysler Neon
 2000 Dodge Neon

This bulletin only applies to vehicles equipped with the factory installed immobilisation system.

Condition: The operator may complain of one or more of the following conditions:

- Intermittent no start.
- Intermittent engine stalling

Cause: A possible cause for this is a Mobile/Esso Speedpass® on the operator's key chain. If the device is held against the ignition key it may interfere with the vehicles anti-theft immobilisation system.

Correction: The Speedpass® device must not be against the key when starting or operating the vehicle. The manufacturer has indicated that no damage will occur to either the vehicle or the Speedpass® device.

REV: 20091216 Corrected typo in application listing.