



TECH TIPS

Dixie Part Numbers: A-6407 A-6516 A-6541 A-6556
 A-6557 A-6571 A-9361 A-9505
 A-9507 S-6246 S-6273

Applications: 2006 – 2007 BMW 3 Series (E90 models)

Condition: The battery-disconnect switch, if removed and installed with the “thin” nut may cause the battery terminal to overheat.

Cause: The “thin” nut that originally held the battery disconnect switch in place does not have a large enough surface area to carry the current to the battery.

Correction: Use a taller nut with a wide flange on the base to ensure that there is a good electrical connection to the terminals.

