



TECH TIPS

Dixie Part Numbers: S-6564 S-80456

Applications: 2007 – 2009 Hyundai Santa Fe 2.7L
2009 – 2010 Hyundai Genesis 3.8L

Condition: The operator of the vehicle may complain that the vehicle is hard to start when the engine is cold and that the engine cranks for an extended period. The malfunction indicator lamp may be illuminated but not in all cases. The technician may observe one or more of the diagnostic trouble codes stored in they system memory P0110, P0111, P0116, P161B, P1295, P2105, P2106 but again, not in all cases.

Cause: A possible cause for the above condition is the engine control module and compatibility with regional fuel additives.

Correction: The manufacturer has released an update for the engine control module software, follow the manufacturer's recommended procedures for verifying if the update is required and performing the update, if required.

