



# TECH TIPS

Dixie Part Numbers:      A-6307      A-8395      S-6526

**Applications:**      1991 Peugeot 405 (Mi 16)

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- Cranks with out starting.
- Various erratic electrical problems.
- Major electrical failure.
- Under hood fire.

**Cause:** A potential cause for the above condition is that the engine wiring harness was routed in close proximity to the alternator and over time may chaff and short circuit to ground.

**Correction:** The manufacturer recommends inspecting the wiring, repairing any damage and re-routing the wiring harness away from the alternator (when applicable).

