



TECH TIPS

Dixie Part Numbers: A-6222 A-9407

Applications: 1992 – 1995 BMW 325 Series
1992 – 1995 BMW 525 Series
1993 – 1995 BMW 320 Series
1995 – 1996 BMW M3 3.0L
1996 – 1999 BMW 328 Series
1996 – 1999 BMW M3 3.2L
1998 – 1999 BMW 323 Series
1999 – 2000 BMW Z3 2.5L
1999 – 2000 BMW Z3 3.0L

Condition: The installer may observe that the hardware used to mount the alternator to the vehicle does not fit with the replacement alternator. The alternator mounting foot for the may not be the same as the one being removed from the vehicle. One of the alternators may have the rear mounting foot threaded and one may not have the threads, as shown in the picture below.



Threaded Rear Mounting Foot



Unthreaded Rear Mounting Foot

Cause: The manufacturer has used the same part number for both threaded and unthreaded mounting feet on this application.

Correction: Dixie has assigned 2 part numbers to the same OE numbers so that the direct replacement alternator can be ordered and installed with no additional hardware required.