



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2011 Cadillac Escalade
(including the ESV and EXT models)

2010 – 2011 Chevrolet Avalanche
2010 – 2011 Chevrolet Silverado
2010 – 2011 Chevrolet Suburban
2010 – 2011 Chevrolet Tahoe
2010 – 2011 GMC Sierra
(including the Denali model)

2010 – 2011 GMC Yukon
(including the Denali, Denali XL and XL models)

Condition: The operator of the vehicle may complain that the message *Battery Low Start Vehicle* is displayed in the driver information center.

Cause: A potential cause for the above condition is the “battery saver mode” programmed into the vehicle’s systems. It was designed to prevent battery run down, however the manufacturer has noted that many users complained that they warning was coming on too soon, such as when starting in cold climates.

Correction: The manufacturer has released a calibration file for the body control module to address this concern. Follow the manufacturer’s recommended procedures for updating the body control module, when applicable.

