



# TECH TIPS

**Dixie Part Numbers:** A-1378 A-1382 A-1401 A-1402

**Applications:** 1992 – 1994 Cadillac DeVille 4.6L and 4.9L applications  
1992 – 1994 Cadillac Eldorado 4.6L and 4.9L applications  
1992 – 1994 Cadillac Seville 4.6L and 4.9L applications

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- A/C compressor moan
- Low alternator output
- Alternator failure

**Cause:** A possible cause for the above conditions is the A/C compressor hose and clutch driver assembly.

**Correction:** The manufacturer has released a revised clutch driver kit and hose kit as shown in the table below to alleviate the problem:

Year	Engine	A/C Compressor Hose Assembly	Clutch Drive Kit
1992	4.9L	25655631	6553791
1993	4.6L	25655633	6553791
1993	4.9L	25655362	6553791
1994	4.9L	3542985	6553791

Follow the manufacturer's recommended procedures when changing the clutch drive kit and a/c compressor hose assembly.