



# TECH TIPS

**Dixie Part Numbers:** S-2124

**Applications:** 2003 – 2005 Ford Excursion 6.0L Diesel  
2003 – 2007 Ford F-Super Duty 6.0L Diesel  
2004 – 2008 Ford E-350, E-450, E-550 6.0L Diesel

**Condition:** The operator of the vehicle may complain of hard starting, failure to start, white smoke, lack of power, rough running after cold start up. The technician may find diagnostic codes P040, P0470, P0611, P1260 and/or P1378 stored in the memory.

**Cause:** A potential cause for the above is an older calibration file in the following modules:

- the Powertrain Control Module
- the Fuel Injector Control Module
- the Transmission Control Module

The new calibration was **not** included in the 2009.3 DVD release of the software.

**Correction:** Update the calibration file using revision 60.05 and higher prior to performing any repairs for the above conditions. Follow the manufacturer's recommended procedures to update the calibration files.