



TECH TIPS

Dixie Part Numbers:	S-2072	S-2073	S-8616	S-8922
	S-80135	TS-1500	TS-1501	TS-1502
	TS-1505	TS-1561	TS-1605	TS-1608
	TS-1611	TS-1625	TS-1626	TS-1683
	TS-6120	201-28116	201-28117	201-37113
	201-37114	201-37138	201-42101	201-42102
	201-42112	201-42113	201-42114	201-42201
	246-25161	260-47274		

Applications: 1994 – 1994 Ford Medium and Heavy Trucks (Cargo, B series, F series and L series equipped with the Allison MD3000 transmission).

Condition: The operator of the vehicle may complain of one or more of the following conditions.

- The vehicle does not start.
- The starter does not engage.
- The starter may engage, disengage, engage as a cycle with the ignition in the start position.

Cause: A potential cause for the above condition may be the incorrect voltage to the Transmission Electrical Control Unit or ECU which will incorrectly sense that the transmission is not in 'neutral' or 'park' thus interrupting the starter operation.

Correction: Verify that the correct voltage is available at the ECU. If low voltage is found check for corrosion and/or loose connections in the circuit. Clean, replace or repair all connections as required.

