



TECH TIPS

Dixie Part Numbers: A-6423 A-6425 A-6426 A-6427
 S-6160 S-6194

Applications: 2005 Volvo XC90

Condition: The operator of the vehicle may experience one or more of the following conditions:

- intermittent electrical problems
- the vehicle fails to start
- the vehicle catches on fire

Cause: A potential cause for the above conditions is an incorrect solenoid installed when the vehicle was manufactured. The solenoid positioned the battery cable against the engine that, after chaffing from vibration could result in a short circuit to ground.

Correction: The above condition was subject to a recall by the manufacturer through the dealership network. The dealers are to replace the starter solenoid and re-route the battery wire.