



TECH TIPS

Dixie Part Numbers:	A-6366	A-6412	A-6423	A-6425
	A-6426	A-6427	A-6546	S-2150
	S-2151	S-6160	S-6194	S-6274

Applications: 2005 – 2006 Volvo S60 with a 2 in the 11th digit of the VIN
2005 – 2006 Volvo S80 with a 1 in the 11th digit of the VIN
2005 – 2006 Volvo V70 with a 1 or 2 in the 11th digit of the VIN
2005 – 2006 Volvo X70 with a 1 in the 11th digit of the VIN
2005 – 2006 Volvo X90 with a 1 in the 11th digit of the VIN
In all cases the production date codes are from 200425 - 200540

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- the engine fails to start
- the brake lights remain on
- various warning lamps remain on
- the headlights remain on, even with the key removed
- various warning messages in the driver information display

Cause: A potential cause for the above condition is an improperly installed seal at the central electric module where the wiring harness enters the plenum (box) containing the module. The improperly installed seal allows moisture to penetrate the plenum.

Correction: The manufacturer made a running change to production. Follow the manufacturer's recommended procedures for inspecting and repairing, and replacing the central electric module if required.