



# TECH TIPS

**Dixie Part Numbers:** S-80192 TBA

**Applications:** 2005 – 2007 Jeep Wrangler 2.8L Diesel\*  
2005 – 2006 Jeep Liberty 2.8L Diesel\*  
2005- 2007 Chrysler/Dodge Voyager 2.8L Diesel\*  
\*Note – Built prior to October 19, 2007 (MDH 1019xx)

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- hard starting
- no starting
- rough idle

**Cause:** A potential cause for the above conditions is too much air in the fuel lines.

**Correction:** Follow the manufacturer's recommended procedure of scanning for diagnostic codes stored in the memory. If none are present then the following parts may require replacing to eliminate the problem:

- Wiring kit (part number 68043086AA)
- Cherokee and Liberty applications fuel filter/water separator (68043089AA)
- 2005 – 2006 Voyager applications fuel filter/water separator (68043089AA)
- 2007 Voyager applications fuel filter/water separator (04721225AE)

Follow the manufacturer's recommended procedures when replacing the above parts.

REV: 20110214 Revised Part Number Listing

REV: 20110214

Courtesy of APRA

TSB\_637.docx

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed without written permission.