



TECH TIPS

Dixie Part Numbers: A-6459 A-8779 A-8781 A-8783
 A-8921 S-8544 S-8751 S-8764

Applications: 2001 Dodge Ram Pickup

Condition: The operator of the vehicle may complain of a failure to start or crank or a low or dead battery. The technician may find a high voltage drop in the alternator positive wiring to the power distribution centre (PDC).

Cause: A potential cause for the above condition is a loose connection from the alternator positive output to the power distribution centre.

Correction: Inspect the terminal connection from the alternator at the power distribution centre and follow the manufacturer's recommended procedure for repositioning and torquing the fastener.

