



TECH TIPS

Dixie Part Numbers:	A-6123	A-6136	A-6137	A-6138
	A-6139	A-6140	A-6141	A-6159
	A-6165	S-6098	S-6069	S-6100
	S-6122	S-6139	S-6140	S-6195

Applications: 1985 – 1990 Volkswagen Golf
1985 – 1990 Volkswagen Jetta
1985 – 1990 Volkswagen Passat

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- There is an insufficient battery charge rate.
- Discharged batteries
- Low alternator output.
- Hard starting.
- A failure to start.
- An intermittent belt squeal.

Cause: A potential cause for the above conditions are water, snow or slush contacting the alternator belt allowing it to slip.

Correction: The manufacture has released splashguards to be put in place over the belts to reduce the water, snow or slush from affecting the belt performance. The dealer part numbers are shown below:

For Golf and Jetta applications: 191-825-0250-01C

For Passat applications: 357-825-254

