



# TECH TIPS

**Dixie Part Numbers:** S-6197 S-6198 S-6241 S-6297  
S-80296 TBA

**Applications:** 2004 Volkswagen Toureg Diesel (BKW Engine)  
2004 – 2005 Volkswagen Jetta Diesel (BEW Engine)  
2004 – 2005 Volkswagen Passat Diesel (BHW Engine)  
2004 – 2006 Volkswagen Beetle Diesel (BEW Engine)  
2004 – 2006 Volkswagen Golf Diesel (BEW Engine)

**Condition:** The operator of the vehicle may complain that the engine is hard to start or fails to start below 0°C (32°F).

**Cause:** A potential cause for the above condition is a software and glow plug flaw, which may cause the glow plugs to not function properly.

**Correction:** The manufacturer had issued a kit which included the injectors, a set of glow plugs and a glow plug control module and new software. Follow the manufacturer's recommended diagnostic and repair procedures when applicable.