



TECH TIPS

Dixie Part Numbers: S-6290

Applications: 2008 Audi A5 Manual Transmission
2008 Audi S5 Manual Transmission

Conditions: The operator of the vehicle may complain that the engine fails to crank or start and the message "To start press clutch is displayed," even though the clutch is pressed. The technician will observe no problems with the clutch hydraulics.

Cause: A potential cause for the above condition is a faulty interlock switch in the clutch master cylinder preventing the starter from activating.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures.

