



TECH TIPS

Dixie Part Numbers:	A-6396	A-6419	A-6513	A-9503
	A-9527	A-9528	A-80205	A-80212
	A-80214	S-6210	S-6263	S-6264
	S-6265	S-6557	S-6558	S-6276
	S-6281	S-6282	S-6290	TBA

Applications: 2004 – 2010 Audi A8*
2005 – 2011 Audi A6*
2007 – 2011 Audi Q7*
2008 – 2011 Audi A4 Cabriolet*
2008 – 2011 Audi A5 Cabriolet*
2009 – 2011 Audi A4*
2009 – 2011 Audi Q5*
* With either Battery Energy Manager (J644) or Battery Diagnostic Manager (J367) options installed

Conditions: The operator of the vehicle may complain of low, discharged batteries, long slow cranking or a failure to start the engine.

Cause: A possible cause for the above conditions is an improperly configured electrical system.

Correction: Follow the manufactures recommended diagnostic and repair procedures.