



TECH TIPS

Dixie Part Numbers: S-6258 S-6259 TBA

Applications: 2008 – 2012 BMW 7 Series (all models)
2009 – 2012 BMW GT/Grand Turismo
2010 – 2012 BMW 5 Series (all models)
2010 – 2012 BMW X3 (all models)
2011 – 2012 BMW 6 Series (all models)

Conditions: The operator of the vehicle may complain that the vehicle does not crank or start. The technician may observe diagnostic trouble code 93070D (internal hardware fault) stored in the car access system module.

Cause: A potential cause for the above is a fault with the car access system module.

Correction: Follow the manufacturer's diagnostic and repair procedures which include first ensuring that the battery is sufficiently charged.