



# TECH TIPS

**Dixie Part Numbers:**      A-8660      A-8661      A-8779      A-8783  
   S-8680      S-8751

**Applications:**      1998 Dodge Durango

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- A low or dead battery
- A failure to crank/start
- A burning smell, smoke and/or fire

The technician may observe a high voltage drop in the alternator positive output cable.

**Cause:** A potential cause for the above condition is a loose connection from the alternator positive output to the power distribution centre.

**Correction:** Follow the manufacturer's recommended procedures to reroute the alternator positive cable and tighten it to the specified torque.

