



# TECH TIPS

**Dixie Part Numbers:** S-80464

**Applications:** 2009 – 2010 Pontiac Vibe  
(US models without the Anti-theft package UA6)

**Condition:** The operator of the vehicle may complain that the starter does not crank on an intermittent basis.

**Cause:** A potential cause for the above condition is that the system is trying to communicate with the immobilizer... which was not installed, causing the system to go into an error.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures if applicable.

