



# TECH TIPS

**Dixie Part Numbers:** A-80032 TBA

**Applications:** 2009 – 2011 Honda Pilot (2 and 4WD) with moon roof

**Condition:** The operator of the vehicle may complain of one or more of the following conditions:

- The battery is low or dead.
- The engine fails to crank or start.
- The battery runs down.
- The moon roof reverses itself while closing

**Cause:** A potential cause for the above condition is that if the vehicle is parked for 2 weeks or longer the parasitic drain that the moon roof puts on the system causes the batteries to run down.

**Correction:** The manufacturer has sent a special “Flash Pack” tool to the dealer network to correct this problem. The dealers, upon completion of the work were to stamp a dot over the vehicle identification number above the first character. Follow the manufacturer’s recommended diagnostic and repair procedures when applicable.