



TECH TIPS

Dixie Part Numbers: A-80431 S-80380 S-80431 TBA

Applications: 2006 – 2011 Chevrolet Caprice (Including PPV models)
2006 – 2011 Chevrolet Lumina (VE and VM models)
2008 – 2010 Pontiac G8

Condition: The technician may observe that the battery cable cap does not come off.

Cause: The cap has 2 locking tabs that must be unlocked before the cap is removed. Failure to unlock the tabs will cause the cap to break.

Correction: Follow the manufacturers recommended procedures for opening the 2 locking tabs and then lift the cap straight out, taking care not to pry on one side at a time... as this too will break the cap.

