



TECH TIPS

Dixie Part Numbers: TBA

Applications:

- 2011 Chrysler Town & Country
- 2011 Dodge Durango
- 2011 Dodge Grand Caravan
- 2011 Dodge Nitro
- 2011 Dodge Ram Pickup (1500, 2500, 3500)
- 2011 Dodge Regular Cab Chassis
- 2011 Jeep Cherokee
- 2011 Jeep Grand Cherokee
- 2011 Jeep Liberty
- 2011 Jeep Wrangler

Conditions: The operator of the vehicle may complain that intermittently the vehicle alarm sounds for no reason and that the vehicle requires numerous attempts before starting. The technician will find diagnostic trouble codes U0001 and U0010 stored in the system

Cause: A potential cause for the above conditions is an error in the totally integrated power module (TIPM) programming logic.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures when applicable which include clearing the codes and updating the software.